

Rov
BWB

December 14, 1976

MEMO TO FILE:

Re: R.D.M.&S. PARTNERSHIP
ACT/045/001

The R.D.M.&S. mine was inspected on the 8th of December by Brian W. Buck and myself. The high grade limestone mine is in the final approval stage but no surety has been posted by the operator, Mr. Jack Madsen of Provo, Utah. Operations in both Bell Canyon and Edwards Canyon were inspected. Only the dip slope mining operation in Bell Canyon was approved under the Notice of Intent.

No activity is presently occurring in Bell Canyon. The site is basically the same as it was observed to be during the last inspection. A small band of sheep are grazing in the area.

In Edwards Canyon road improvements have been performed on Sec. 4, T. 9 S., R. 3 W. In addition, a small assessment trench or equipment pad was excavated at the roads end. The road improvement work has been performed with no apparent drainage damage and by removing very little earth, only the road surface was regraded.

No workmen were present in either Bell or Edwards Canyon.

DIVISION OF OIL, GAS, AND MINING

RONALD W. DANIELS, COORDINATOR
OF MINED LAND DEVELOPMENT

RWD/lc